ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0148, W0318, W0397, W0314, W0393

Street Name
NA, 1st Crs, V S T Opposite, 3rd Crs

Significant Landmark
Basavanna temple surroundings Doddabommasandra ol

Segment No.
10/S-W0148/S084312

Total Length (m)
156.57

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	115.10	77.552095	13.062277	77.553120	13.062007	W0065	DEAD END
2	15.02	77.558501	13.059670	77.558487	13.059535	W0314	DEAD END
3	26.45	77.558233	13.059739	77.558469	13.059679	W0393	W0397

Work Details

History of Road / Lane / Circles

Name of the Work
Estimate for Providing cc roads at Basavanna temple surroundings Doddabommasandra old village in ward no 10 Doddabommasandra Vidyaranayapura Sub-Di

Sanctioned Estimated Amount (Rs.)
1500000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Estimate for Providing cc roads at Basavanna temple surroundings Doddabommasandra old village in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-16-000005

Work Order No.
EE/BTP/BBMP/E-PMT/WO/199/2015-16

Work Order Date
05/02/2016

Period of Extention
90 DAYS

Defect Liability Period From
05/02/2016

Defect Liability Period To
04/02/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

K V SUBBAREDDY	0.00

Phone No. **E-Mail ID**

9980915550

Field Inspection Details

Number of Trees	Any Other Information	Name
0		MADHAV RAO
Date of Inspection	**Remarks**	
21/09/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0148, W0318, W0397, W0314,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	21/09/2016	21/10/2016	COMPLETED
SE	VASU K M	21/09/2016	21/10/2016	COMPLETED
EE	YARAPPA REDDY	21/09/2016	21/10/2016	COMPLETED
AEE	SHIVAKUMAR	21/09/2016	21/10/2016	COMPLETED
AE	MADHAV RAO	21/09/2016	21/10/2016	COMPLETED
AE	MADHAV RAO	21/09/2016	21/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0148, W0318, W0397, W0314,